## TO BE FILLED BY THE INSPECTING OFFICER

- 1. Name of School : Bhavan's Vidyashram, Chelembra Name of the Officer : Subeesh C S, Asst. Engineer LSGD Section, Chelembra Grama Panchayat 2. Location : Chelembra 3. Period for which the Certificate is issued : 2023-24 4. Type of Building : GF-RC Building 1) 27.30 X 10.90 X 3.60 13.93 X 9.23 X 3.60 5 Class room FF-RC Building 2) 27.30 X 10.90 X 3.60 13.93 X 9.23 X 3.60 5 Class room SF Sheet Proof 3) 27.30 X 10.90 X 3.60 13.93 X 9.23 X 3.60 5 Class room 5. Nature of defect if any a. Foundation and basement b. Superstructure c. Doors and windows : Nil d. Wood work wrought and put up e. Roof f. Flooring g. Miscellaneous (cracks if any) 6. Any major defects notice which will render the building unsafe if any manner : No 7. Whether maintenance work have been done properly : Yes 8. Whether the structure is sound or not for Conducting classes : The structure is sound for conducting classes under normal wind and weather conditions. Note 1. The stability of the structure should be examined also with reference to location attitude intensity of wind exposure to flood etc.
  - 2. Any additional observation if deemed necessary for the certificate may be furnished Separately with the certificate.

Certificate that the school was inspected by me on  $3^{\circ}/s^{2^{\circ}}$  and found to be fit/-unfit to conduct classes for the reasons stated above.

HE ASSIST

SECTIC

Abcretary & Director Haratiya Vidya Bhavan

Ramanattukara Kendra

ate Chelember Place: Chelembra Date: 30/5/2023

AN, RAMAN

P.B. No: 8

Ramanattukara 673633

tant Engineer As. L.S.G.D Section Chelembra Grama Panchayath

PRINCIPAL E r avan's Vidyashram Affin.No:930465 Chelembra,Malappuram Dt. Kerala,India, Pin: 673 634 Ph:0483 2890532

